

# LÖWE

TECHNICALLY  
ADVANCED  
FORMULATION

98.5%  
ZINC PURITY

## GLV-90

### COLD GALVANISING ZINC

- PROTECTS AGAINST RUST & CORROSION
- EXCELLENT ADHESION • HIGH ZINC CONTENT

#### GLV-90 COLD GALVANISING ZINC SPRAY

- COMBINES THE SUPERIOR RUST INHIBITING PROPERTIES OF ZINC WITH A TOUGH ENAMEL COATING.
- FOR LONG-TERM PROTECTION OF STEEL COMPONENTS SUCH AS IRON, IRON PIPES, STEEL CONTAINERS, OUTDOOR SIGNS ETC.
- IDEAL FOR RE-GALVANISING AND REPAIRING DAMAGED SPOTS ON GALVANISED PARTS AS WELL AS ON WELDING AND CUTTING POINTS IN STEEL CONSTRUCTION.



#### CURUST INDUSTRIES LTD.

Units 12 & 13,  
Southern Cross  
Business Park,  
Bray,  
Co. Wicklow, Ireland.  
Tel: +353 | 276 0800.  
Fax: +353 | 276 0799.  
email: info@curust.ie  
www.curust.ie

### 400ml

#### PREPARATION

Surface should be cleaned from dirt, dust, oil, rust flakes etc or any other contaminants that may prevent the anodization process. If painting over previously painted surfaces check for compatibility on a small area first.

#### APPLICATION

Invert can and shake vigorously for 2 minutes after the agitator ball starts to rattle. Shake frequently during use. Hold upright and spray from a distance of approximately 15-30cm. Apply in light even layers. When repairing damaged surfaces apply 2-3 coats. If a topcoat with a specific colour is required, allow a minimum of 6 hours drying time before applying the topcoat. Avoid applying at temperatures below 10C or in damp conditions. Always clear nozzle after use by inverting the can and spraying for 3 seconds or until only propellant is expelled.

#### DRYING TIME

Touch dry in 15 minutes at 20C. Fully cured in approximately 24 hrs at 20C. Overspray can be cleaned with Douglas White Spirits.



#### UN 1950 AEROSOLS:

Extremely flammable aerosol.

Pressurised container: May burst or explode if heated.

Do not get in eyes, on skin or on clothing. Causes serious eye irritation. Repeated exposure may cause skin dryness or cracking. Harmful to aquatic life with long lasting effects.

Wear suitable protective clothing and only use in well ventilated areas.

IF IN EYES: Rinse cautiously with water for several minutes, remove lenses if present and easy to do. Continue rinsing.

IF SWALLOWED: Rinse mouth. Do not induce vomiting.

Avoid breathing fumes, mists vapours or spray. May cause drowsiness or dizziness.

Get medical advice/attention if you feel unwell.

Keep away from heat, sparks, open flames and hot surfaces. No smoking.

Do not spray on an open flame or other ignition sources.

Protect from sunlight. Do not expose to temperatures exceeding 50C.

Keep out of reach of children. Use only as directed.

Do not pierce or burn, even after use.

Dispose of contents and container in accordance with local regulations.



**DANGER**